

Get Your Heads Examined!

With VideoMagnetics' New Video Head Health Checkup



Quad Head Checkup for Ampex and RCA \$250.00

- Measure Headwheel tips for head life:
 - If head has usable life with
 - Ferrite—1.2 to 2.6 mil range
 - Metal— 1.8 to 2.6 mil range
 - We'll Measure Control Track Head Wear and Placement.
 - Adjust Quad Headwheel Balance and Quadrature Error
 - Replace Worn Gaskets.
 - Make sure head interchanges properly for playback
- If head assembly is worn or needs additional work, IE: Transformer, thrust and bearing, guide or guide edge damage repair customer will be advised of costs.
- If after adjustments the head does not meet specifications, a complete refurbishment will be recommended. The \$250.00 inspection cost will be deducted from the refurbishing cost if customer has the work done while head is still at VMI.

Sony 1" Upper Drum Checkup \$125.00

- Measure Head Tips for head life.
- Anything under 34um will be considered unusable and will have to be refurbished.
- If Head Tips are still usable but Upper Drum is damaged, we will remove Tips and Carriers, and buff out drum.
- If after buffing the Upper Drum, it meets specifications, we will reassemble and calibrate the Upper Drum for \$500.00
- If Drum does not meet interchange specifications we can replace the Drum for additional \$250.00

Sony 1" Type C Scanner Assembly Checkup \$250.00

- Includes inspection and scanner recalibration
- If worn parts such as Slip Rings or Brushes are needed, parts needed will determine cost.
- If Lower Drum bearings are bad and Upper Drum is still good, we will advise about your options. Refurbishment: \$5200.00

Sony 3/4" U-Matic Upper Drum Checkup \$250.00

- See Sony 1" Type-C Upper Drum Checkup for details. Pricing as needed

Sony 3/4" U-Matic Scanner Assembly Checkup \$250.00

- See Sony 1" Type-C Complete Scanner Assembly Checkup for details.

Ask how our "SteadyFlow™" Quantity Head Rebuilding Program saves money!



Representing products from creative companies
Ted Langdell, CEO
Mobile • (530) 301-2931 Office • (530) 741-1212



Ampex 1" Type C Head Checkup \$50.00

Check condition, Tip Life

- All SIX Heads: AST, R/P Erase and Dummies

Ampex 1" Type C Scanner Ass'y Checkup \$250.00

- Includes Inspection and Re-calibration. We'll advise of any worn parts needing replacement and additional costs.
- If Lower Drum bearings are bad, but Head Tips and Upper Drum are still good, a Complete Scanner Refurbishment to factory specs or better is only \$4,200.00

ted@flashscan8.us

www.flashscan8.us

209 East 12th Street, Marysville, CA 95901

fs8.us-VMI-HeadExam-V2-09-20-2011